

## OsmoTRX - Bug #3341

### osmo-trx-lms RF Envelope FAIL on LimeSDR, but not on LimeSDR-mini

06/13/2018 01:46 PM - laforge

<b>Status:</b> In Progress	<b>Start date:</b> 06/13/2018
<b>Priority:</b> High	<b>Due date:</b>
<b>Assignee:</b> roh	<b>% Done:</b> 70%
<b>Category:</b> LimeSDR	
<b>Target version:</b>	
<b>Spec Reference:</b>	
<b>Description</b> I'm observing a strange behavior when comparing the RF envelope of osmo-trx-lms on a LimeSDR and a LimeSDR-mini. The LimeSDR-mini envelope is within spec. Specifically, the transmit power level is at full strength before the start of the next burst. SCREEN1.BMP SCREEN2.BMP On the LimeSDR however, the next burst/timeslot starts too late, (or the slew rate is too low?): SCREEN3.BMP SCREEN4.BMP This is using the exact same versions of LimeSuite (f1e5444496923890ad7d030abef9c224c37c46cf) and osmo-trx (70621b74844a6ea08d6da5f5b1e1835b9af91771). All I'm doing is swapping the hardware and re-starting osmo-trx-lms and osmo-bts. It's very odd, and I currently have no clue of what might be going on here.	
<b>Related issues:</b>	
Related to OsmoTRX - Feature #2919: Native LimeSDR support	<b>Resolved</b> 02/09/2018
Blocked by OsmoTRX - Bug #3775: properly debug limesdr usb and limesdr mini c...	<b>In Progress</b> 01/31/2019

#### History

##### #1 - 06/14/2018 07:02 AM - laforge

- Related to Feature #2919: Native LimeSDR support added

##### #2 - 07/03/2018 03:13 PM - laforge

- Assignee set to roh

[roh](#): please re-perform the LimeSDR (non-mini) tests using a LimeSDR that is clocked from the 10MHz reference of the E4406.

Please also try to modify the `ts_offset` found in the following line of the source code in `osmo-trx/Transceiver52M/device/lms/LMSDevice.cpp`:

```
ts_offset = static_cast<TIMESTAMP>(8.9e-5 * GSMRATE * tx_sps); /* time * sample_rate */
```

##### #3 - 07/04/2018 12:58 PM - laforge

- Priority changed from Normal to High

##### #4 - 08/08/2018 11:13 AM - laforge

ping?

**#5 - 08/17/2018 01:20 PM - laforge**

- Priority changed from High to Immediate

**#6 - 08/17/2018 05:36 PM - roh**

- File limesdr\_usb\_871.png added

- % Done changed from 0 to 10

still debugging on a full limesdr usb. using today's nightly builds.

i am using this config:

```
log stderr
 logging filter all 1
 logging color 1
 logging print category 1
 logging timestamp 1
 logging print file basename
 logging level all info
 logging level main notice
 logging level lms notice
 logging level lglobal notice
 logging level llapd notice
 logging level linp notice
 logging level lmux notice
 logging level lmi notice
 logging level lmib notice
 logging level lsms notice
 logging level lctrl notice
 logging level lgtp notice
 logging level lstats notice
 logging level lgsup notice
 logging level loop notice
 logging level lss7 notice
 logging level lscpp notice
 logging level lsua notice
 logging level lm3ua notice
 logging level lmgcp notice
 logging level ljibuf notice
!
stats interval 5
!
line vty
 no login
!
trx
 bind-ip 127.0.0.1
 remote-ip 127.0.0.1
 rx-sps 4
 clock-ref external
 multi-arfcn disable
 swap-channels disable
 egprs disable
 rt-prio 18
 chan 0
 rx-path LNAW
 tx-path BAND1
```

i've seen it crash once' but sadly i don't have a complete log: (the intention was to find the "Setting External clock reference" line.

```
/usr/bin/osmo-trx-lms -C /etc/osmocom/osmo-trx-lms.cfg 2>&1 |grep -i ref
Reference..... 1
Fri Aug 17 19:09:30 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] Estimated reference clock 30.6588
MHz
Fri Aug 17 19:09:30 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] Reference clock 30.72 MHz
```

```

Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 5000.00 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 4800.00 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2400.00 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2400.00 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2218.67 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2218.67 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:31 2018 DMAIN <0000> LMSDevice.cpp:158 [tid=139746895380288] Setting External clock reference
to 1e+07
Fri Aug 17 19:09:32 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] MCU Ref. clock: 30.72 MHz
Fri Aug 17 19:09:32 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2334.72 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:32 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] MCU Ref. clock: 30.72 MHz
Fri Aug 17 19:09:32 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895380288] VCO 2334.72 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:34 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895599360] VCO 7128.00 MHz, RefClk 30.72 MHz
Fri Aug 17 19:09:34 2018 DLMS <0001> LMSDevice.cpp:74 [tid=139746895599360] VCO 7508.00 MHz, RefClk 30.72 MHz
telnet_connection          contains      1 bytes in   1 blocks (ref 0) 0x5620c10659c0
logging                    contains    2014 bytes in   7 blocks (ref 0) 0x5620c0ff86f0
struct trx_ctx             contains     383 bytes in   5 blocks (ref 0) 0x5620c0ff7410
msgb                       contains      0 bytes in   1 blocks (ref 0) 0x5620c0ff73a0
telnet_connection          contains      1 bytes in   1 blocks (ref 0) 0x5620c10659c0
logging                    contains    2014 bytes in   7 blocks (ref 0) 0x5620c0ff86f0
  logging.c:1033           contains     937 bytes in   1 blocks (ref 0) 0x5620c1034cb0
  logging.c:950            contains     196 bytes in   1 blocks (ref 0) 0x5620c1034b80
  struct log_target        contains     200 bytes in   2 blocks (ref 0) 0x5620c0ff8ae0
    struct log_category    contains      40 bytes in   1 blocks (ref 0) 0x5620c0ff8bf0
  struct log_info          contains     680 bytes in   2 blocks (ref 0) 0x5620c0ff8760
    struct log_info_cat    contains     640 bytes in   1 blocks (ref 0) 0x5620c0ff87f0
struct trx_ctx             contains     383 bytes in   5 blocks (ref 0) 0x5620c0ff7410
  BAND1                    contains      6 bytes in   1 blocks (ref 0) 0x5620c1065eb0
  LNAW                     contains      5 bytes in   1 blocks (ref 0) 0x5620c1065a30
  127.0.0.1                contains     10 bytes in   1 blocks (ref 0) 0x5620c0ff7660
  127.0.0.1                contains     10 bytes in   1 blocks (ref 0) 0x5620c0ff75e0
msgb                       contains      0 bytes in   1 blocks (ref 0) 0x5620c0ff73a0

```

so far i have not been able to get it running well enough so the 4406 will do a gmsk phase and frequency plot. pwr vs time screenshot below. most the time i cannot even get it to trigger properly.

the clock output on the limesdr seems to be disabled (no signal according to the scope)

even in the case of osmo-trx-lms continuing to run the rf signal isnt visible on the 4406 anymore after 3-5 minutes.

the output of osmo-trx-lms keeps printing this kind of information one line per second tho.

```

Fri Aug 17 19:25:22 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1189661
Fri Aug 17 19:25:23 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1189877
Fri Aug 17 19:25:24 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1190094
Fri Aug 17 19:25:25 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1190310
Fri Aug 17 19:25:26 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1190527
Fri Aug 17 19:25:27 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140577027438336] ClockInterface: sending IND C
LOCK 1190743

```

to get it working it is *not* enough to restart osmo-trx-lms. one has also to physically disconnect the limesdr-usb and reconnect it.

LimeQuickTest

[ TESTING STARTED ]

->Start time: Fri Aug 17 19:32:53 2018

->Device: LimeSDR-USB, media=USB 3.0, module=FX3, addr=1d50:6108, serial=0009060B00472227

Serial Number: 0009060B00472227

[ Clock Network Test ]

->FX3 GPIF clock test

Test results: 28260; 32016; 35772 - PASSED

->Si5351C test

CLK0: 17554 / 17554 - PASSED

```

CLK1: 17554 / 17554 - PASSED
CLK2: 17554 / 17554 - PASSED
CLK3: 17554 / 17554 - PASSED
CLK4: 17554 / 17554 - PASSED
CLK5: 17554 / 17554 - PASSED
CLK6: 17554 / 17554 - PASSED
->ADF4002 Test
  Result: 10 - PASSED
->VCTCXO test
  Results : 5112948 (min); 5113078 (max) - PASSED
->Clock Network Test PASSED

[ FPGA EEPROM Test ]
->Read EEPROM
->Read data: 11 05 11 11 05 11 02
->FPGA EEPROM Test PASSED

[ LMS7002M Test ]
->Perform Registers Test
->External Reset line test
  Reg 0x20: Write value 0xFFFFD, Read value 0xFFFFD
  Reg 0x20: value after reset 0xFFFF
->LMS7002M Test PASSED

[ RF Loopback Test ]
->Configure LMS
->Run Tests (TX_2-> LNA_L):
  CH0 (SXR=800.0MHz, SXT=805.0MHz): Result:(-15.1 dBFS, 5.00 MHz) - PASSED
  CH1 (SXR=800.0MHz, SXT=805.0MHz): Result:(-17.1 dBFS, 5.00 MHz) - PASSED
->Run Tests (TX_1 -> LNA_W):
  CH0 (SXR=1800.0MHz, SXT=1805.0MHz): Result:(-19.2 dBFS, 5.00 MHz) - PASSED
  CH1 (SXR=1800.0MHz, SXT=1805.0MHz): Result:(-17.9 dBFS, 5.00 MHz) - PASSED
->Run Tests (TX_2-> LNA_H):
  CH0 (SXR=2500.0MHz, SXT=2505.0MHz): Result:(-16.7 dBFS, 5.00 MHz) - PASSED
  CH1 (SXR=2500.0MHz, SXT=2505.0MHz): Result:(-14.7 dBFS, 5.00 MHz) - PASSED
->RF Loopback Test PASSED

=> Board tests PASSED <=

Elapsed time: 1.87 seconds

```

the installed limesuite is 18.06 from the debian nightly feeds (everything updated today)  
the limesdr usb got updated by using 'LimeUtil --update' (also today)

version dumping in osmo-trx-lms seems still broken:

```

usr/bin/osmo-trx-lms -C /etc/osmocom/osmo-trx-lms.cfg -V
Info: SSE3 support compiled in and supported by CPU
Info: SSE4.1 support compiled in and supported by CPU
OsmoTRX version UNKNOWN

```

i will repeat these tests with limesdr-mini now.

limesdr mini seems not to accept the clock external command:

```
/usr/bin/osmo-trx-lms -C /etc/osmocom/osmo-trx-lms.cfg
Info: SSE3 support compiled in and supported by CPU
Info: SSE4.1 support compiled in and supported by CPU
Fri Aug 17 19:59:35 2018 DLGLOBAL <0002> telnet_interface.c:104 telnet at 127.0.0.1 4237
Fri Aug 17 19:59:35 2018 DLCTRL <0009> control_if.c:887 CTRL at 127.0.0.1 4236
Config Settings
  Log Level..... 1
  Device args.....
  TRX Base Port..... 5700
  TRX Address..... 127.0.0.1
  GSM BTS Address..... 127.0.0.1
  Channels..... 1
  Tx Samples-per-Symbol... 4
  Rx Samples-per-Symbol... 4
  EDGE support..... 0
  Reference..... 1
  C0 Filler Table..... 1
  Multi-Carrier..... 0
  Tuning offset..... 0
  RSSI to dBm offset..... 0
  Swap channels..... 0
  Tx Antennas..... 'BAND1'
  Rx Antennas..... 'LNAW'

Setting SCHED_RR priority(18)
Fri Aug 17 19:59:35 2018 DMAIN <0000> LMSDevice.cpp:49 [tid=140719660293952] creating LMS device...
Fri Aug 17 19:59:35 2018 DMAIN <0000> LMSDevice.cpp:99 [tid=140719660293952] Opening LMS device..
Fri Aug 17 19:59:35 2018 DMAIN <0000> LMSDevice.cpp:105 [tid=140719660293952] Devices found: 1
Fri Aug 17 19:59:35 2018 DMAIN <0000> LMSDevice.cpp:115 [tid=140719660293952] Device [0]: LimeSDR Mini, media=
USB 3.0, module=FT601, addr=24607:1027, serial=1D3C03216CC90D
Fri Aug 17 19:59:35 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Claimed Interface
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Estimated reference clock 40.0015
MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Reference clock 40.00 MHz
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:126 [tid=140719660293952] Init LMS device
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 121, FRAC 0, DIV_LOCH 1, EN_DI
V2_DIVPROG 0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 5000.00 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=64 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=96 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=112 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=120 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=124 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=126 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=127 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Failed to lock
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=192 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=224 cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=240 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=232 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=228 cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=230 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=229 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Failed to lock
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOL : csw=226 tune ok
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] TuneVCO(SXT) - VCO too high
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOM : csw=0 tune fail
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] TuneVCO(SXT) - VCO too high
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOH : csw=0 tune fail
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Selected: VCOL
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 116, FRAC 0, DIV_LOCH 1, EN_DI
V2_DIVPROG 0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 4800.00 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=64 cmphl=0
```

```

Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=96 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=112 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=120 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=124 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=126 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=127 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Failed to lock
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=192 cmphl=0
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=224 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=208 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=200 cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=204 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=202 cmphl=3
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw=201 cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] CSW: lowest=198, highest=201, selected=199
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] cmphl=2
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOL : csw=199 tune ok
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] TuneVCO(SXR) - VCO too high
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOM : csw=0 tune fail
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] ICT_VCO: 180
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] TuneVCO(SXR) - VCO too high
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCOH : csw=0 tune fail
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Selected: VCOL
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 57, FRAC 385875, DIV_OUTCH_CGEN 18
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 2334.72 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw 155; interval [152, 159]
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 57, FRAC 385875, DIV_OUTCH_CGEN 18
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 2334.72 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw 155; interval [152, 159]
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] M=160, N=4, Fvco=614.400 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] M=160, N=4, Fvco=614.400 MHz
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:85 [tid=140719660293952] Sample Rate: Min=100000 Max=3.072e+07 Step=0
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:136 [tid=140719660293952] Setting sample rate to 1.08333e+06 4
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 54, FRAC 489335, DIV_OUTCH_CGEN 7
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 2218.67 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw 129; interval [125, 133]
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] INT 54, FRAC 489335, DIV_OUTCH_CGEN 7
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] VCO 2218.67 MHz, RefClk 40.00 MHz
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] csw 129; interval [125, 133]
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:142 [tid=140719660293952] Sample Rate: Host=1.08333e+06 RF=3.46667e+07
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:158 [tid=140719660293952] Setting External clock reference to 1e+07
Fri Aug 17 19:59:36 2018 DLMS <0001> LMSDevice.cpp:74 [tid=140719660293952] Command not supported
Fri Aug 17 19:59:36 2018 DMAIN <0000> LMSDevice.cpp:205 [tid=140719660293952] Error in LMS open, closing: Command not supported
Fri Aug 17 19:59:36 2018 DMAIN <0000> osmo-trx.cpp:453 [tid=140719660293952] Failed to create radio device
Shutting down transceiver...

```

**#8 - 08/17/2018 06:17 PM - laforge**

roh wrote:

limesdr mini seems not to accept the clock external command:  
[...]

Please file this as bug at <https://github.com/myriadrf/LimeSuite/issues>

**#9 - 08/17/2018 06:18 PM - roh**

it seems a limesdr mini behaves similar to a -usb after it 'stopped working' (no signal on rf) when one does comment the "clock-ref external" from the config.

commenting out the rx and tx path from the config does not change anything visible.

**#10 - 08/24/2018 03:01 PM - roh**

- File *usrp\_usb871\_env.png* added

- File *usrp\_usb871\_phase.png* added

i did some comparison tests with a usrp and the same software builds used to generate the lms measurements. (just swapping osmo-trx-lms for osmo-trx-uhd)  
the results seem flawless and pass the 4406.

versions used:

OsmoBTS version 0.8.1.37-2222  
Osmo-PCU version 0.5.1.1-54af  
OsmoTRX version UNKNOWN <- uhd  
linux; GNU C++ version 6.3.0 20170221; Boost\_106200; UHD\_003.009.005-0-unknown  
OsmoTRX version UNKNOWN <- lms  
OsmoBSC version 1.3.0.34-0c877  
OsmoGGSN version 1.2.2.9-ee44  
OsmoMGW version 1.4.0.13.9a7c  
OsmoSGSN version 1.3.0.32-c503f  
OsmoSTP version 0.10.0.4-39fd  
OsmoMSC version 1.2.0.46-381370  
OsmoHLR version 0.2.1.47-1eb9

this install is about 1 week old and uses nightly images from our debian package feed.

my next experiment is to use a second system to downgrade the lms hardware to older gateway/firmware

#11 - 08/24/2018 04:07 PM - roh

- File limesdr\_usb\_871\_lms1706\_env.png added

- % Done changed from 10 to 20

i flashed firmware from <http://downloads.myriadrf.org/project/limesuite/17.12/> to the limeSDR-USB by copying it to `~/local/share/LimeSuite/images/17.12/` symlinking it to 18.06 and symlinking LimeSDR-USB\_HW\_1.4\_r2.14.rbf to LimeSDR-USB\_HW\_1.4\_r2.17.rbf (otherwise LimeUtil --update would not flash these files but the global installed ones from 18.06)

i reset the sdr (un- and replug) and redid the tests from last week.

results are basically the same. the signal slope is out of bounds, the 4406 has a hard time syncing at all on the bursts and i could not get it to trigger well enough for a phase plot.  
shot attached.

it was stable for like 20 minutes and i actually saw a rollover on the clock indication output but now it failed with a device timeout.

```
....
Fri Aug 24 17:57:49 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140620449900288] ClockInterface: sending IND C
LOCK 2613878
Fri Aug 24 17:57:50 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140620449900288] ClockInterface: sending IND C
LOCK 2614095
Fri Aug 24 17:57:51 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140620449900288] ClockInterface: sending IND C
LOCK 2614312
Fri Aug 24 17:57:51 2018 DMAIN <0000> LMSDevice.cpp:517 [tid=140620449900288] LMS: Device receive timed out
Fri Aug 24 17:57:51 2018 DMAIN <0000> radioInterface.cpp:319 [tid=140620449900288] Receive error 1620
Fri Aug 24 17:57:52 2018 DMAIN <0000> LMSDevice.cpp:515 [tid=140620449900288] chan 0 recv buffer of len 0 expe
ct eef5b4c got 0 (0) diff=fffffffff110a4b4
Fri Aug 24 17:57:52 2018 DMAIN <0000> LMSDevice.cpp:517 [tid=140620449900288] LMS: Device receive timed out
Fri Aug 24 17:57:52 2018 DMAIN <0000> radioInterface.cpp:319 [tid=140620449900288] Receive error 0
Fri Aug 24 17:57:52 2018 DMAIN <0000> LMSDevice.cpp:515 [tid=140620449900288] chan 0 recv buffer of len 0 expe
ct eef5b4c got 0 (0) diff=fffffffff110a4b4
Fri Aug 24 17:57:52 2018 DMAIN <0000> LMSDevice.cpp:517 [tid=140620449900288] LMS: Device receive timed out
Fri Aug 24 17:57:52 2018 DMAIN <0000> radioInterface.cpp:319 [tid=140620449900288] Receive error 0
Fri Aug 24 17:57:52 2018 DMAIN <0000> LMSDevice.cpp:515 [tid=140620449900288] chan 0 recv buffer of len 0 expe
ct eef5b4c got 0 (0) diff=fffffffff110a4b4
...
Fri Aug 24 17:57:58 2018 DMAIN <0000> LMSDevice.cpp:517 [tid=140620449900288] LMS: Device receive timed out
Fri Aug 24 17:57:58 2018 DMAIN <0000> radioInterface.cpp:319 [tid=140620449900288] Receive error 0
Fri Aug 24 17:57:58 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140620450166528] command is POWEROFF
Fri Aug 24 17:57:58 2018 DMAIN <0000> Transceiver.cpp:292 [tid=140620450166528] Stopping the transceiver
Fri Aug 24 17:57:58 2018 DMAIN <0000> LMSDevice.cpp:515 [tid=140620449900288] chan 0 recv buffer of len 0 expe
ct eef5b4c got 0 (0) diff=fffffffff110a4b4
Fri Aug 24 17:57:58 2018 DMAIN <0000> LMSDevice.cpp:517 [tid=140620449900288] LMS: Device receive timed out
terminate called without an active exception
signal 6 received
talloc report on 'OsmoTRX' (total 2398 bytes in 15 blocks)
telnet_connection contains 1 bytes in 1 blocks (ref 0) 0x55bd6b01bda0
logging contains 2014 bytes in 7 blocks (ref 0) 0x55bd6afaeaf0
struct trx_ctx contains 383 bytes in 5 blocks (ref 0) 0x55bd6afae410
msgb contains 0 bytes in 1 blocks (ref 0) 0x55bd6afae3a0
full talloc report on 'OsmoTRX' (total 2398 bytes in 15 blocks)
telnet_connection contains 1 bytes in 1 blocks (ref 0) 0x55bd6b01bda0
logging contains 2014 bytes in 7 blocks (ref 0) 0x55bd6afaeaf0
logging.c:1033 contains 937 bytes in 1 blocks (ref 0) 0x55bd6afeb090
logging.c:950 contains 196 bytes in 1 blocks (ref 0) 0x55bd6afeaf60
struct log_target contains 200 bytes in 2 blocks (ref 0) 0x55bd6afae0e0
struct log_category contains 40 bytes in 1 blocks (ref 0) 0x55bd6afaeff0
struct log_info contains 680 bytes in 2 blocks (ref 0) 0x55bd6afae6b0
struct log_info_cat contains 640 bytes in 1 blocks (ref 0) 0x55bd6afae6f0
struct trx_ctx contains 383 bytes in 5 blocks (ref 0) 0x55bd6afae410
BAND1 contains 6 bytes in 1 blocks (ref 0) 0x55bd6b01c290
LNAW contains 5 bytes in 1 blocks (ref 0) 0x55bd6b01be10
127.0.0.1 contains 10 bytes in 1 blocks (ref 0) 0x55bd6afae660
127.0.0.1 contains 10 bytes in 1 blocks (ref 0) 0x55bd6afae5e0
msgb contains 0 bytes in 1 blocks (ref 0) 0x55bd6afae3a0
Aborted
```

i do not believe it was a cable issue since i am using quite short, and well shielded usb3 cables and was not shuffling around on them at the time.

just downgrading to 17.12 lms firmware does not seem to solve the issue



**#12 - 08/27/2018 04:30 PM - roh**

- File deleted (limesdr\_usb\_871\_lms1706\_env.png)

**#13 - 08/27/2018 04:31 PM - roh**

- File limesdr\_usb\_871\_lms1712\_env.png added

**#14 - 08/27/2018 04:47 PM - roh**

i tried repeating the tests with 2017.09 firmware, but could not find the correct images on <http://downloads.myriadrf.org/project/limesuite/17.09/>

there is either no firmware support for V1.4 hardware in limesuite 17.09 or i don't know which images to flash (limesdr usb needs 2 files. one .img and one .rbf)

see <http://downloads.myriadrf.org/project/limesuite/17.09/> and its neighbours

**#15 - 08/27/2018 05:08 PM - roh**

opened a issue on github about the clocking option missing in firm/gateway <https://github.com/myriadrf/LimeSuite/issues/213>

**#16 - 08/28/2018 02:11 PM - roh**

i repeated the test with the limesdr-mini (v1.1) with firmware from limesuite 18.04 (LimeSDR-Mini\_HW\_1.1\_r1.24.rpd)

there is some kind of carrier like with 18.06 but the 4406 cannot sync/trigger on it at all.

**#17 - 08/28/2018 05:33 PM - roh**

note to self: limesdr usb ref clock output needs to be enabled first by placing a resistor on R151 ([https://github.com/myriadrf/LimeSDR-USB/blob/master/hardware/plug/1v4/Project%20Outputs%20for%20LimeSDR-USB\\_1v4\\_LMS031pad/LimeSDR-USB\\_1v4\\_schematic\\_r7.PDF](https://github.com/myriadrf/LimeSDR-USB/blob/master/hardware/plug/1v4/Project%20Outputs%20for%20LimeSDR-USB_1v4_LMS031pad/LimeSDR-USB_1v4_schematic_r7.PDF) page 14)

**#18 - 09/04/2018 01:19 PM - roh**

i just tested osmo-trx-lms nightly against limesuite18.06 from the packages and against a fresh limesuite build from today

in both cases the signal slope on the limesdr-usb looks awful (see limesdr\_usb\_871.png or limesdr\_usb\_871\_lms1712\_env.png)

i could not yet test the -mini since i currently have this issue updating the fw: (with the same cables which work for -usb)

```
root@test123:~/src# LimeUtil --update
Connected to [LimeSDR Mini [USB 3.0] 1D3C03216CC90D]
Read(64 bytes) failed
Update not supported: UNKNOWN[HW=0]
```

```
Programming update failed! : Update not supported: UNKNOWN[HW=0]
```

#19 - 09/04/2018 03:46 PM - roh

- File 00001.png added

- File limesdr\_mini\_871\_no\_modulation.gif added

- File limesdr\_mini\_871\_no\_modulation\_waveform.gif added

i checked 3 limesdr-mini v1.1 now, of which one is working (with \$unknown firmware version) somehow, but not correctly (no visible tx carrier anywhere near the intended arfcn)

instead i can see a wideband burst for a short while when i start osmo-trx-lms:

```
/usr/bin/osmo-trx-lms -C /etc/osmocom/osmo-trx-lms.cfg
Info: SSE3 support compiled in and supported by CPU
Info: SSE4.1 support compiled in and supported by CPU
Tue Sep  4 16:32:51 2018 DLGLOBAL <0003> telnet_interface.c:104 telnet at 127.0.0.1 4237
Tue Sep  4 16:32:51 2018 DLCTRL <000a> control_if.c:887 CTRL at 127.0.0.1 4236
Config Settings
  Log Level..... 3
  Device args.....
  TRX Base Port..... 5700
  TRX Address..... 127.0.0.1
  GSM BTS Address..... 127.0.0.1
  Channels..... 1
  Tx Samples-per-Symbol... 4
  Rx Samples-per-Symbol... 4
  EDGE support..... 0
  Reference..... 0
  C0 Filler Table..... 1
  Multi-Carrier..... 0
  Tuning offset..... 0
  RSSI to dBm offset..... 0
  Swap channels..... 0
  Tx Antennas..... 'BAND1'
  Rx Antennas..... 'LNAW'

Setting SCHED_RR priority(18)
Tue Sep  4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:49 [tid=140694087274304] creating LMS device...
Tue Sep  4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:99 [tid=140694087274304] Opening LMS device..
Tue Sep  4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:105 [tid=140694087274304] Devices found: 1
Tue Sep  4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:115 [tid=140694087274304] Device [0]: LimeSDR Mini, media=U
SB 3.0, module=FT601, addr=24607:1027, serial=1D3ACA1B10B681
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Claimed Interface
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Estimated reference clock 40.0013
MHz
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Reference clock 40.00 MHz
Tue Sep  4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:126 [tid=140694087274304] Init LMS device
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 121, FRAC 0, DIV_LOCH 1, EN_DI
V2_DIVPROG 0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 5000.00 MHz, RefClk 40.00 MHz
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=64      cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=96      cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=112     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=120     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=124     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=126     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=127     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Failed to lock
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=192     cmphl=0
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=224     cmphl=2
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=240     cmphl=3
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=232     cmphl=3
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=228     cmphl=3
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=226     cmphl=2
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=227     cmphl=2
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] CSW: lowest=222, highest=227, sele
cted=224
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] cmphl=2
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOL : csw=224 tune ok
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] TuneVCO(SXT) - VCO too high
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOM : csw=0 tune fail
Tue Sep  4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
```

```

Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] TuneVCO(SXT) - VCO too high
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOH : csw=0 tune fail
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Selected: VCOL
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 116, FRAC 0, DIV_LOCH 1, EN_DI
V2_DIVPROG 0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 4800.00 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=64 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=96 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=112 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=120 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=124 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=126 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=127 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Failed to lock
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=192 cmphl=0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=224 cmphl=3
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=208 cmphl=3
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=200 cmphl=2
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=204 cmphl=3
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=202 cmphl=3
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw=201 cmphl=3
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Failed to lock
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] cmphl=2
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOL : csw=198 tune ok
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] TuneVCO(SXR) - VCO too high
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOM : csw=0 tune fail
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] ICT_VCO: 180
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] TuneVCO(SXR) - VCO too high
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCOH : csw=0 tune fail
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Selected: VCOL
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 57, FRAC 385875, DIV_OUTCH_CGE
N 18
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2334.72 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 155; interval [152, 159]
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 57, FRAC 385875, DIV_OUTCH_CGE
N 18
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2334.72 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 155; interval [152, 159]
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] M=160, N=4, Fvco=614.400 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] M=160, N=4, Fvco=614.400 MHz
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:85 [tid=140694087274304] Sample Rate: Min=100000 Max=3.072e
+07 Step=0
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:136 [tid=140694087274304] Setting sample rate to 1.08333e+0
6 4
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 54, FRAC 489335, DIV_OUTCH_CGE
N 7
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2218.67 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 128; interval [124, 132]
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 54, FRAC 489335, DIV_OUTCH_CGE
N 7
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2218.67 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 128; interval [124, 132]
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:142 [tid=140694087274304] Sample Rate: Host=1.08333e+06 RF=
3.46667e+07
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:149 [tid=140694087274304] Setting Internal clock reference
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:153 [tid=140694087274304] Setting VCTCXO to 180
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:85 [tid=140694087274304] LPFBWRange Rx: Min=1.4001e+06 Max=
1.3e+08 Step=0
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:85 [tid=140694087274304] LPFBWRange Tx: Min=1.4001e+06 Max=
1.3e+08 Step=0
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:177 [tid=140694087274304] LPFBW: Rx=1.4001e+06 Tx=5.2e+06
Tue Sep 4 16:32:51 2018 DMAIN <0000> LMSDevice.cpp:203 [tid=140694087274304] Antennas configured successfully
Tue Sep 4 16:32:51 2018 DDEV <0001> LMSDevice.cpp:186 [tid=140694087274304] Setting LPFBW chan 0
Tue Sep 4 16:32:51 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 10 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU Ref. clock: 40 MHz
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 191 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] RX LPF configured
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 57, FRAC 385875, DIV_OUTCH_CGE
N 18
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2334.72 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 155; interval [152, 159]

```

```

Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU Ref. clock: 40 MHz
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 61 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Filter calibrated. Filter order=4t
h, filter bandwidth set to 5.2 MHz.Real pole 1st order filter set to 2.5 MHz. Preemphasis filter not active
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] INT 57, FRAC 385875, DIV_OUTCH_CGE
N 18
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] VCO 2334.72 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] csw 155; interval [152, 159]
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] TX LPF configured
Tue Sep 4 16:32:54 2018 DDEV <0001> LMSDevice.cpp:191 [tid=140694087274304] Calibrating chan 0
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:54 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 97 ms
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] Rx calibration finished
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 0 ms
Tue Sep 4 16:32:55 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087274304] MCU algorithm time: 84 ms
-- Transceiver active with 1 channel(s)
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is POWEROFF
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is RXTUNE 1782000
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] INT 85, FRAC 104857, DIV_LOCH 1, E
N_DIV2_DIVPROG 1
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCO 7128.00 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] TuneVCO(SXR) - VCO too low
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOL : csw=0 tune fail
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] TuneVCO(SXR) - VCO too low
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOM : csw=0 tune fail
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=64 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=96 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=112 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=120 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=124 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=126 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=127 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Failed to lock
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=192 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=160 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=144 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=152 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=156 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=158 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=157 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Failed to lock
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOH : csw=146 tune ok
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Selected: VCOH
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is TXTUNE 1877000
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] INT 89, FRAC 891289, DIV_LOCH 1, E
N_DIV2_DIVPROG 1
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCO 7508.00 MHz, RefClk 40.00 MHz
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] TuneVCO(SXT) - VCO too low
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOL : csw=0 tune fail
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] TuneVCO(SXT) - VCO too low
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOM : csw=0 tune fail
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] ICT_VCO: 180
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=64 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=96 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=112 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=120 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=124 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=126 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=127 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Failed to lock
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=192 cmphl=0
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=224 cmphl=3

```

```

Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=208 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=216 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=220 cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=222 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] csw=221 cmphl=3
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Failed to lock
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] cmphl=2
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] VCOH : csw=211 tune ok
Tue Sep 4 16:32:56 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140694087501568] Selected: VCOH
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETTSC 7
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:811 [tid=140694087501568] Changing TSC from 0 to 7
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is POWERON
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:238 [tid=140694087501568] Starting the transceiver
Tue Sep 4 16:32:56 2018 DMAIN <0000> radioInterface.cpp:168 [tid=140694087501568] Starting radio device
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:212 [tid=140694087501568] starting LMS...
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:315 [tid=140694087501568] Setting TX gain to 36.5 dB.
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:335 [tid=140694087501568] Setting RX gain to 34 dB.
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:382 [tid=140694087501568] Initial timestamp 27500
Tue Sep 4 16:32:56 2018 DMAIN <0000> radioInterface.cpp:189 [tid=140694087501568] Radio started
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETRXGAIN 1
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:335 [tid=140694087501568] Setting RX gain to 1 dB.
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1599964
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETPOWER 1
Tue Sep 4 16:32:56 2018 DDEV <0001> LMSDevice.cpp:315 [tid=140694087501568] Setting TX gain to 72 dB.
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 0 5
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 1 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 2 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 3 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 4 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 5 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 6 1
Tue Sep 4 16:32:56 2018 DMAIN <0000> Transceiver.cpp:709 [tid=140694087501568] command is SETSLOT 7 1
Tue Sep 4 16:32:57 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1600180
Tue Sep 4 16:32:58 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1600397
Tue Sep 4 16:32:59 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1600613
Tue Sep 4 16:33:00 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1600830
Tue Sep 4 16:33:01 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1601046
Tue Sep 4 16:33:02 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1601263
Tue Sep 4 16:33:03 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1601479
Tue Sep 4 16:33:04 2018 DMAIN <0000> Transceiver.cpp:1018 [tid=140694087227136] ClockInterface: sending IND C
LOCK 1601696
^Csignal 2 received
shutting down
Shutting down transceiver...
Tue Sep 4 16:33:05 2018 DMAIN <0000> Transceiver.cpp:292 [tid=140694087274304] Stopping the transceiver
Tue Sep 4 16:33:05 2018 DMAIN <0000> Transceiver.cpp:305 [tid=140694087274304] Stopping the device
Tue Sep 4 16:33:05 2018 DMAIN <0000> Transceiver.cpp:318 [tid=140694087274304] Transceiver stopped
libusb: warning [libusb_exit] application left some devices open

```

the burst is happening a short time before the "ClockInterface: sending IND CLOCK" messages start coming through. see screenshot.

on the second device which i modified for 10mhz input i cannot get the application started (10mhz external clock is connected)

```

root@test123:~/src# /usr/bin/osmo-trx-lms -C /etc/osmocom/osmo-trx-lms.cfg
Info: SSE3 support compiled in and supported by CPU
Info: SSE4.1 support compiled in and supported by CPU
Tue Sep 4 17:19:16 2018 DLGLOBAL <0003> telnet_interface.c:104 telnet at 127.0.0.1 4237
Tue Sep 4 17:19:16 2018 DLCTRL <000a> control_if.c:887 CTRL at 127.0.0.1 4236
Config Settings
  Log Level..... 3
  Device args.....
  TRX Base Port..... 5700
  TRX Address..... 127.0.0.1

```

```
GSM BTS Address..... 127.0.0.1
Channels..... 1
Tx Samples-per-Symbol... 4
Rx Samples-per-Symbol... 4
EDGE support..... 0
Reference..... 1
C0 Filler Table..... 1
Multi-Carrier..... 0
Tuning offset..... 0
RSSI to dBm offset..... 0
Swap channels..... 0
Tx Antennas..... 'BAND1'
Rx Antennas..... 'LNAW'
```

Setting SCHED\_RR priority(18)

```
Tue Sep  4 17:19:16 2018 DDEV <0001> LMSDevice.cpp:49 [tid=140019953102656] creating LMS device...
Tue Sep  4 17:19:16 2018 DDEV <0001> LMSDevice.cpp:99 [tid=140019953102656] Opening LMS device..
Tue Sep  4 17:19:16 2018 DDEV <0001> LMSDevice.cpp:105 [tid=140019953102656] Devices found: 1
Tue Sep  4 17:19:16 2018 DDEV <0001> LMSDevice.cpp:115 [tid=140019953102656] Device [0]: LimeSDR Mini, media=U
SB 3.0, module=FT601, addr=24607:1027, serial=1D3C03216CC90D
Tue Sep  4 17:19:16 2018 DLMS <0002> LMSDevice.cpp:74 [tid=140019953102656] Claimed Interface
Tue Sep  4 17:19:17 2018 DDEV <0001> LMSDevice.cpp:126 [tid=140019953102656] Init LMS device
Tue Sep  4 17:19:17 2018 DDEV <0001> LMSDevice.cpp:128 [tid=140019953102656] LMS_Init() failed
Tue Sep  4 17:19:17 2018 DMAIN <0000> osmo-trx.cpp:453 [tid=140019953102656] Failed to create radio device
Shutting down transceiver...
libusb: warning [libusb_exit] application left some devices open
```

i assume this is due to the broken firmware state (all 3 devices do not allow updating via LimeUtil --update)

the 3rd device (with internal clock again) starts on osmo-trx-lms, but the resulting spectrum seems to be a unmodulated sine carrier.  
see screenshots.

the tests today were all done with a LimeSuite build from git ef2625631a02b29dfbcbe172ed88d1bb92f7a0ca built into debian packages and used with osmo-trx-lms OsmoTRX version 0.4.0 from our nightly builds



**#21 - 09/20/2018 01:29 PM - laforge**

- Status changed from New to Stalled

**#22 - 10/16/2018 04:37 PM - roh**

- File `limesdr_usb_871_phase_lms1810.gif` added

- File `limesdr_usb_871_env_lms1810.gif` added

all these tests were done with a limesdr usb sn:0009060B00472227 and external 10mhz clock from the E4406A rx LNAW tx BAND1

- updated all software (limesuite is now 18.10)
- tested with osmo-trx-lms - result was signal but after a few seconds without any busts! (cw carrier)
- updated limesdr usb from gateway version 2, revision 17 to revision 18.
- tested with osmo-trx-lms - results in a minimal more stable setup. this does NOT qualify as 'PASS' on the 4406 either. i could not get enough burst lock to get a phase measurement, but the slope shot is attached

interestingly i could actually attach 2 phones in the resulting network and get a voicecall to work for a moment, but one of the devices was much more prone to loose the network (motorola). the (old) nokia had less trouble there. (more robust error handling?)

**#23 - 10/17/2018 05:05 PM - roh**

compared testsetups with pau - same results like my last measurements.

after some time i still have 'missing bursts' behaviour (no sync anymore, cw signal visible on free-running sync) on -14dBm

this is repeatable after restarting the process with a cw at +12dBm

osmo-bts-trx.cfg:

```
osmotrx rx-gain 1
osmotrx tx-attenuation 1
```

osmo-bsc.cfg

```
! arfcn 871
arfcn 5
nominal power 23
max_power_red 10
```

to 'fix' it again i need to un- and replug the limesdr-usb (hardware reset)

the resulting signal (if its not CW) has a power of ~3.2dBm in this setup.

on gsm900 i have had a bit better results on getting the 4406 to sync on the 'bursts' which are produced for some time, but the switch-to-cw is the same in that band.

osmo-trx-lms.cfg (for reference)

```
!
! OsmoTRX (UNKNOWN) configuration saved from vty
!!
!
```



```
log stderr
  logging filter all 1
  logging color 1
  logging print category 1
  logging timestamp 1
  logging print file basename
  logging level all info
  logging level main notice
  logging level lms notice
  logging level lglobal notice
  logging level llapd notice
  logging level linp notice
  logging level lmx notice
  logging level lmi notice
  logging level lmib notice
  logging level lsms notice
  logging level lctrl notice
  logging level lgtp notice
  logging level lstats notice
  logging level lgsup notice
  logging level loap notice
  logging level lss7 notice
  logging level lsccp notice
  logging level lsua notice
  logging level lm3ua notice
  logging level lmgcp notice
  logging level ljibuf notice
!
stats interval 5
!
line vty
  no login
!
trx
  bind-ip 127.0.0.1
  remote-ip 127.0.0.1
  rx-sps 4
  tx-sps 4
  clock-ref external
  multi-arfcn disable
  swap-channels disable
  base-port 5700
  egprs disable
  rt-prio 18
  chan 0
  rx-path LNAW
  tx-path BAND1
```

**#24 - 10/20/2018 08:27 PM - ptrkrysik**

- File *openbsc.cfg* added
- File *osmo-bts.cfg* added
- File *osmo-trx-limesdr.cfg* added
- File *LimeQuickTest* added
- File *LimeUtil\_info* added

In the setup I have osmo-trx runs constantly with LimeSDR for whole the time I did test it, which is over 3 hours. It worked correctly at least on Tx side  
- gr-gsm is able to decode the signal correctly. I didn't check the Rx side yet.

My setup:

I'm running osmo-nitb.  
The config files for openbsc, open-bts and osmo-trx are in the attachments.

I also attached output of "LimeQuickTest" and "LimeUtil --info" commands.

Software revisions:

libosmocore: 73b7fa61096c  
osmo-trx: e7d267f17883  
osmo-bts: 12ee1e12b3a1  
openbsc: cd8c5f3fa4ee  
limesuite: eff75aef81f2

In case more information is needed please ask.

If someone would share a software setup and config files for which LimeSDR failed, I could try to test it with my LimeSDR.

**#25 - 10/21/2018 03:34 AM - duo\_kali**

- File *LimeQuicktest* added
- File *LimeUtil --info* added

in my tested: (strange result actually for rfloopback on LNAH but work for the rest)

It was failed on LNAH RFloopback LimeQuickTest (but we are not going test on that freq on GSM anyway)

I've downgrade the Limesuite to 17.09 which use latest osmo-trx-lms. using this gateway: (the most stable for me)  
[http://downloads.myriadrf.org/project/limesuite/17.09/LimeSDR-USB\\_HW\\_1.3\\_r3.0.img](http://downloads.myriadrf.org/project/limesuite/17.09/LimeSDR-USB_HW_1.3_r3.0.img)  
[http://downloads.myriadrf.org/project/limesuite/17.09/LimeSDR-USB\\_HW\\_1.4\\_r2.9.rbf](http://downloads.myriadrf.org/project/limesuite/17.09/LimeSDR-USB_HW_1.4_r2.9.rbf)

(testing also with 18.10 which is fine for me for osmo-trx-lms site), using this gateway:  
[http://downloads.myriadrf.org/project/limesuite/18.10/LimeSDR-USB\\_HW\\_1.4\\_r4.0.img](http://downloads.myriadrf.org/project/limesuite/18.10/LimeSDR-USB_HW_1.4_r4.0.img)  
[http://downloads.myriadrf.org/project/limesuite/18.10/LimeSDR-USB\\_HW\\_1.4\\_r2.18.rbf](http://downloads.myriadrf.org/project/limesuite/18.10/LimeSDR-USB_HW_1.4_r2.18.rbf)

The result for GSM network: (TX = BAND1, RX= LNAL)

900mhz and 1800mhz run constantly then test the call fine with all 5 subscribers which connection never failed in the start or in the middle of osmo-trx running and the longest network stay running for 18-24 hours and test call again after I woke up from sleep and keep it a try and seems all phone

keep stay in the network with LimeSDR-USB until I switched off (using legacy osmo-nitb and new splits both also tested).

another test:

LimeSDR-USB using USB.3 has interference with other electricity (which has big watt) and make osmo-trx failed in the middle of connection, example as using other things (tools with big watt in same power plug source). you need to unplug and replug for make connection again. but it was fine when using USB.3 with only laptop attached to powerplug source alone with LimeSDR.

USB.2 are fine and no interference on USB.2 port.

But using USB2 cable in USB3 port, the downlink modulation waveform is changing continuously (sound from GQRX), which causing phone also hard to camped to the network.

#### #26 - 10/21/2018 06:09 AM - duo\_kali

- File LimeUtil --info 1810 added

This is the tested when phone camped and call between phone using latest LimeSuite 18.10 with newest gateway I mention above. Its running latest osmo-trx-lms with New Splits (current master):

<https://streamable.com/xehra>

its running stable constantly with USB3 cable in USB3 Port. TX=BAND1, RX=LNAL in 1800MHZ.

#### #27 - 10/21/2018 07:23 AM - ptrkrysik

I can't reproduce the issue with LimeSDR-USB stopping to work after several minutes. I checked two of them without being able to obtain the problem.

If I would have both working and not working setup it would allow me to identify what might cause the problem. Could someone share the configs and software revisions for which this problem was encountered on LimeSDR-USB?

#### #28 - 10/23/2018 02:31 PM - roh

i continued my experiments with lime-usb:

using usb2 only (forced by adding a usb2 only power meter in the line) i could make the following observations:

- the device pulls 500-700mA constantly, regardless of the tx state
- the device has usb structures filled to announce itself as 'bus powered' and 100mA (no external feed connected, the board is in a metal enclosure) thus violating usb spec.
- the device can be listed by 'lsusb -d 1d50:6108' properly all the time (regardless of usb2 or usb3)
- the device fails immediately (see below) when using 'lsusb -d 1d50:6108 -v' and connected to usb2. this does not fail when connected via usb3!
- failing does also generate a CW carrier as long as osmo-trx-lms keeps running (it does till it gets killed even when constantly in the state as logged below)

```
...
Tue Oct 23 16:27:25 2018 DMAIN <0000> Transceiver.cpp:1038 [tid=139643218388736] ClockInterface: sending IND C
LOCK 183676
Tue Oct 23 16:27:26 2018 DMAIN <0000> Transceiver.cpp:1038 [tid=139643218388736] ClockInterface: sending IND C
LOCK 183893
Tue Oct 23 16:27:26 2018 DDEV <0001> LMSDevice.cpp:520 [tid=139643218388736] chan 0 recv buffer of len 2500 ex
```

```
pect 246e2c got 248218 (248218) diff=13ec
Tue Oct 23 16:27:26 2018 DDEV <0001> LMSDevice.cpp:520 [tid=139643218388736] chan 0 recv buffer of len 2500 ex
pect 2477f0 got 248bdc (248bdc) diff=13ec
...
```

#### #29 - 10/23/2018 03:35 PM - roh

note:

my last few measurements (16.10 to now) were all taken with LimeSDR-USB\_HW\_1.4\_r2.18.rbf and LimeSDR-USB\_HW\_1.4\_r4.0.img from limesuite 18.10

#### #30 - 10/24/2018 08:42 AM - ptrkrysik

On my side LimeSDR-USB was powered from two USB ports with use of cable that was supplied together with the device. One port was USB3.0 (to which Lime's data lines were connected) and additional port was USB2.0.

#### #31 - 10/25/2018 06:37 AM - ptrkrysik

I checked also if BTS based on LimeSDR-USB is able to maintain calls. To test it I made silent calls to a real mobile phone. They didn't break anything either.

#### #32 - 11/26/2018 03:05 PM - laforge

- Status changed from Stalled to In Progress

- % Done changed from 20 to 70

the root cause of this seemed to be that we're not using the full scale of the sample/dac.

There's #define LIMESDR\_TX\_AMPL 0.3 which basically means we're using only 30% of the scale (0.3\*32767 for the signed 16bit integer). We compensate that by using a lot of analog tx gain (up to 73?).

We tested with LIMESDR\_TX\_AMPL 1.0 and reducing analog tx gain to about 60 dB (tx-attenuation of 12: 73 - 12 = 61) and the RF envelope looked excellent compared to before - both on LimeSDR-USB and LimeSDR-mini.

The remaining unrelated problem is related to the phase error not passing the E4406, which apparently can be achieved by tuning the PLL settings. The phase error in the 900 MHz band is OK, while the phase error in 1800 was fail (rms > 5 degrees).

#### #33 - 11/27/2018 10:57 AM - roh

some more experiments resulted in

```
// this was 0.3 before - values above 0.8 generate more phase noise, values below 0.6 give too much amplitude noise(not enough resolution) to pass
gmsk validation on a E4406
#define LIMESDR_TX_AMPL 0.7
```

#34 - 11/27/2018 12:29 PM - roh

pushed a patch to Gerrit

<https://gerrit.osmocom.org/#/c/osmo-trx/+/11949/>

#35 - 11/29/2018 07:15 AM - Zack

Definition of LIMESDR\_TX\_AMPL limits maximum amplitude of I and Q channels separately. Hence LIMESDR\_TX\_AMPL value must be  $1/\sqrt{2} = 0.7071\dots$  to get an amplitude of 1 of the complex signal:

$$A^2 = I^2 + Q^2$$

$$A^2 = (1/\sqrt{2})^2 + (1/\sqrt{2})^2$$

$$A^2 = 1/2 + 1/2$$

$$A^2 = 1$$

Hence if you assign LIMESDR\_TX\_AMPL to be more than  $1/\sqrt{2}$ , complex amplitude is greater than 1 and leads to the issues.

#36 - 11/29/2018 12:30 PM - laforge

- Priority changed from Immediate to High

See <https://gerrit.osmocom.org/#/c/osmo-trx/+/12006/> <https://gerrit.osmocom.org/#/c/osmo-trx/+/12007/>  
<https://gerrit.osmocom.org/#/c/osmo-trx/+/12008/>

[roh](#) please re-test using those changes, and **without** using any 'osmotrx tx-attenuation' in your config files

#37 - 01/23/2019 01:33 PM - laforge

laforge wrote:

[roh](#) please re-test using those changes, and **without** using any 'osmotrx tx-attenuation' in your config files

ping?

#38 - 01/23/2019 08:59 PM - roh

i tried to get the clock issue on limesdr mini resolved first:

<https://github.com/myriadrf/LimeSuite/issues/213> says its fixed.

sadly there is no documentation (i found) about what kind of signal (slope, amplitude) the external clock should be.

some experiments gained that a sinusoidal clock with 40MHz is completely ignored as long as its smaller than ~3dBm. 3-6dBm seem to work for now. also one needs to completely restart the device for every test (replug usb), since it will not start up when the clock is not available on reset. this experiment was done on a limesdr mini serial 0x1d42568b4d0f48 which was updated to gateway 28 just before moving the resistor to enable the external input.

i could not get the modified limesdr mini v1.1 serial 0x1d3c03216cc90d to work. (led stays off) i guess it needs to be unbricked by jtag first.

so far i can only get it to 'work' with 40mhz clock. all other clocks do not allow LimeQuickTest to run at all. even with 40mhz i can not get it to 'PASS' the clock section:

```
[ Clock Network Test ]
->REF clock test
  Test results: 1498; 14695; 27892 - PASSED
->VCTCXO test
  Results : 6711179 (min); 6711179 (max) - FAILED
  FAILED
->Clock Network Test FAILED
```

i am not sure whats up with this, but i am recompiling osmo-lms-trx to test it against 40mhz external clock for now.

how one should be able to use anything different than 40mhz when that is what the fpga needs to get configured and controlled is not obvious to me yet.

#### #39 - 01/23/2019 10:20 PM - roh

osmo-trx-lms works when using a patch which changes the expected external clock from 10mhz to 40mhz. phase errors are a bit too high, for a pass yet. may need more work on pga settings to see if the phase noise can be reduced.

#### #40 - 01/28/2019 02:57 PM - roh

phase noise on limesdr mini is ok for 900mhz band.

on the dcs 1800 band i can not get it to pass quality requirements, even with reduced tx-gain (experiment used '64dB' +/-10db)

#### #41 - 01/29/2019 05:30 PM - roh

it seems the clockchip used on lime mini (ti LMK00105) is not happy with sinewaves and wants *sharp* rectangles 2V/ns or better.

this means i need to redo all these measurements as soon as i have a clockgenerator with proper rectangle output.

**#42 - 01/31/2019 05:56 PM - roh**

- File limesdr\_mini\_5\_env\_lms1810git\_extclock10.gif added
- File limesdr\_mini\_5\_env\_lms1810git\_extclock10\_tx-att\_9.gif added
- File limesdr\_mini\_5\_phase\_lms1810git\_extclock10.gif added
- File limesdr\_mini\_5\_phase\_lms1810git\_extclock10\_tx-att\_9.gif added
- File limesdr\_mini\_871\_env\_lms1810git\_extclock10.gif added
- File limesdr\_mini\_871\_env\_lms1810git\_extclock10\_tx-att\_9.gif added
- File limesdr\_mini\_871\_phase\_lms1810git\_extclock10.gif added
- File limesdr\_mini\_871\_phase\_lms1810git\_extclock10\_tx-att\_9.gif added

new measurement series:

arfcn 5 and arfcn 871, envelope and phase. all done with limesdr mini 1.2, on external 10MHz reference clock (square wave, slope see [#3775](#))

please note: tx-att\_9 files are done with a tx-power of '64dB' (lms api setting). the files without are done on '73dB' (full power)

**#43 - 02/14/2019 04:33 PM - roh**

- Blocked by Bug #3775: properly debug limesdr usb and limesdr mini clocking requirements and osmo-trx support added

**Files**

SCREEN1.BMP	46.6 KB	06/13/2018	laforge
SCREEN2.BMP	43.2 KB	06/13/2018	laforge
SCREEN3.BMP	48.3 KB	06/13/2018	laforge
SCREEN4.BMP	43.9 KB	06/13/2018	laforge
limesdr_usb_871.png	15 KB	08/17/2018	roh
usrp_usb871_env.png	15.4 KB	08/24/2018	roh
usrp_usb871_phase.png	18.2 KB	08/24/2018	roh
limesdr_usb_871_lms1712_env.png	16.5 KB	08/27/2018	roh
00001.png	17.6 KB	09/04/2018	roh
limesdr_mini_871_no_modulation.gif	17.7 KB	09/04/2018	roh
limesdr_mini_871_no_modulation_waveform.gif	15.7 KB	09/04/2018	roh
limesdr_usb_871_phase_lms1810.gif	17.4 KB	10/16/2018	roh
limesdr_usb_871_env_lms1810.gif	17.2 KB	10/16/2018	roh
osmo-bts.cfg	687 Bytes	10/20/2018	ptrkrysik
openbsc.cfg	3.14 KB	10/20/2018	ptrkrysik
osmo-trx-limesdr.cfg	331 Bytes	10/20/2018	ptrkrysik
LimeUtil_info	360 Bytes	10/20/2018	ptrkrysik
LimeQuickTest	2.02 KB	10/20/2018	ptrkrysik
LimeQuicktest	2.02 KB	10/21/2018	duo_kali
LimeUtil --info	651 Bytes	10/21/2018	duo_kali
LimeUtil --info 1810	645 Bytes	10/21/2018	duo_kali
limesdr_mini_5_env_lms1810git_extclock10.gif	17.3 KB	01/31/2019	roh
limesdr_mini_5_env_lms1810git_extclock10_tx-att_9.gif	16.7 KB	01/31/2019	roh
limesdr_mini_5_phase_lms1810git_extclock10.gif	25.7 KB	01/31/2019	roh
limesdr_mini_5_phase_lms1810git_extclock10_tx-att_9.gif	23 KB	01/31/2019	roh
limesdr_mini_871_env_lms1810git_extclock10.gif	17 KB	01/31/2019	roh
limesdr_mini_871_env_lms1810git_extclock10_tx-att_9.gif	17.5 KB	01/31/2019	roh
limesdr_mini_871_phase_lms1810git_extclock10.gif	26.4 KB	01/31/2019	roh
limesdr_mini_871_phase_lms1810git_extclock10_tx-att_9.gif	26.1 KB	01/31/2019	roh