

UmTRX - Feature #1514

Solder mask is not enough reliable against re-soldering few times

02/19/2016 10:52 PM - 9600

Status:	Closed	Start date:	
Priority:	High	Due date:	
Assignee:	Andrey	% Done:	0%
Category:	Hardware	Spec Reference:	
Target version:	UmTRXv2.2		
Resolution:	fixed		
Description			
Solder mask is not enough reliable against re-soldering few times.			
[Migrated from old Google Code tracker]			

History

#1 - 05/29/2014 05:52 PM - Andrey

- Status changed from New to Closed

- Resolution set to fixed

In the [UmTRX](#) v2.2 and 2.3 under the LMS's around GND pad has been added lines on the silk layer over the all hidden VIAs.