

## Miscellaneous Projects - Bug #64

### osmo-bts-amp: 2.2uF capacitors next to PA need to be 0603, not 0805

02/19/2016 10:47 PM - laforge

<b>Status:</b>	New	<b>Start date:</b>	
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	tnt	<b>% Done:</b>	0%
<b>Category:</b>			
<b>Target version:</b>			
<b>Spec Reference:</b>			
<b>Description</b>			
0805 capacitors are typically higher than the PA module and would thus interfere with mounting it against a heatsink. Thus, we're using 0603 capacitors in 2.2uF, and the footprint can (and should) be shrunk from the current 0805			

#### History

##### #1 - 02/21/2016 04:48 PM - laforge

- Project changed from OpenBSC to Miscellaneous Projects
- Subject changed from 2.2uF capacitors next to PA need to be 0603, not 0805 to osmo-bts-amp: 2.2uF capacitors next to PA need to be 0603, not 0805
- Category deleted (osmo-bts-amp)