

SIMtrace - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Related issues |
|------|---------|----------|----------|---|------------|---------------------|----------------|
| 2614 | Bug | Rejected | Normal | simtrace_hdr randomly appears in APDU payload | lukash | 09/28/2022 08:06 AM | |
| 1864 | Support | Closed | Normal | Windows drivers | | 12/07/2016 10:06 AM | |
| 1840 | Bug | Closed | Normal | SIMtrace Firmware | laforge | 11/22/2016 05:56 PM | |
| 1456 | Bug | Closed | Normal | make sure there is solder mask between pads of SAM7 | tsaitgaist | 02/20/2016 06:39 PM | |
| 1451 | Feature | Closed | Normal | Atmel SAM3S to replace SAM7S | tsaitgaist | 02/20/2016 06:40 PM | |
| 1438 | Feature | Closed | Normal | add ID-1 slot to SIMtrace | tsaitgaist | 02/20/2016 06:42 PM | |
| 1436 | Feature | Closed | Normal | add VCC_PHONE to an unused GPIO | tsaitgaist | 02/20/2016 06:42 PM | |
| 1435 | Bug | Closed | Normal | sim card detect does not work (SW_SIM) | tsaitgaist | 02/20/2016 06:43 PM | |
| 1433 | Feature | Closed | Normal | use 90 degree angled jumpers for ERASE and TEST | tsaitgaist | 02/20/2016 06:44 PM | |
| 1432 | Bug | Closed | Normal | simtrace: bootloader switch without function | tsaitgaist | 02/20/2016 06:44 PM | |
| 1430 | Feature | Closed | Normal | clearly indicate location of 'pin 1' of components and connectors | tsaitgaist | 02/20/2016 06:44 PM | |
| 1429 | Feature | Closed | Normal | usb jack type is really hard to manually solder | tsaitgaist | 02/20/2016 06:44 PM | |
| 1428 | Feature | Closed | Normal | increase default trace width in simtrace pcb | tsaitgaist | 02/20/2016 06:44 PM | |
| 1426 | Bug | Closed | Normal | simtrace component names on silk screen unreadable | tsaitgaist | 02/20/2016 06:44 PM | |