

## SIMtrace - Issues

| #    | Tracker | Status   | Priority  | Subject   | Assignee   | Updated             | Related issues |
|------|---------|----------|-----------|---|------------|---------------------|----------------|
| 1840 | Bug     | Closed   | Normal    | SIMtrace Firmware   | laforge    | 11/22/2016 05:56 PM |                |
| 1459 | Bug     | Resolved | Low       | send a flag tagging the ATR from the card                                 | laforge    | 02/06/2021 01:32 PM |                |
| 2614 | Bug     | Rejected | Normal    | simtrace_hdr randomly appears in APDU payload                             | lukash     | 09/28/2022 08:06 AM |                |
| 1456 | Bug     | Closed   | Normal    | make sure there is solder mask between pads of SAM7                       | tsaitgaist | 02/20/2016 06:39 PM |                |
| 1452 | Bug     | Closed   | High      | move C14 directly to pad 4 of IC2   | tsaitgaist | 02/20/2016 06:40 PM |                |
| 1450 | Bug     | Closed   | Urgent    | FTDI serial connector power supply  | tsaitgaist | 02/20/2016 06:40 PM |                |
| 1449 | Bug     | Closed   | High      | no solder mask between the pads of the AT91SAM7                           | tsaitgaist | 02/20/2016 06:41 PM |                |
| 1448 | Bug     | Closed   | High      | silk screen print on top of soldering pads                                | tsaitgaist | 02/20/2016 06:41 PM |                |
| 1447 | Bug     | Closed   | High      | C14 is too far from LDO, causes oscillation                               | tsaitgaist | 02/20/2016 06:41 PM |                |
| 1446 | Bug     | Closed   | High      | test ticket to check notification   | tsaitgaist | 02/20/2016 06:41 PM |                |
| 1437 | Bug     | Closed   | Immediate | on resistance of bus switch not acceptable, at least not for Vcc          | tsaitgaist | 02/20/2016 06:42 PM |                |
| 1435 | Bug     | Closed   | Normal    | sim card detect does not work (SW_SIM)                                    | tsaitgaist | 02/20/2016 06:43 PM |                |
| 1434 | Bug     | Closed   | High      | socket for FPC SIM adapter is mechanically incompatible with rebelsim fpc | tsaitgaist | 02/20/2016 06:43 PM |                |
| 1432 | Bug     | Closed   | Normal    | simtrace: bootloader switch without function                              | tsaitgaist | 02/20/2016 06:44 PM |                |
| 1431 | Bug     | Closed   | High      | use PA16 for UDP_PUP as required by SAM-BA                                | tsaitgaist | 02/20/2016 06:44 PM |                |
| 1427 | Bug     | Closed   | High      | simtrace BC847 footprint has B / E switched                               | tsaitgaist | 02/20/2016 06:44 PM |                |
| 1426 | Bug     | Closed   | Normal    | simtrace component names on silk screen unreadable                        | tsaitgaist | 02/20/2016 06:44 PM |                |
| 1425 | Bug     | Closed   | High      | simtrace pinout of bootloader / reset switch is wrong                     | tsaitgaist | 02/20/2016 06:44 PM |                |
| 1424 | Bug     | Closed   | High      | simtrace pinout of tps73633 is wrong                                      | tsaitgaist | 02/20/2016 06:45 PM |                |