

## Issues

| #    | Project                         | Tracker | Status      | Priority | Subject  | Assignee               | Updated             | Related issues  |
|------|---------------------------------|---------|-------------|----------|--|------------------------|---------------------|---|
| 1458 | OsmocomBB                       | Bug     | New         | High     | AGC broken (strong cell cannot be synced)                                      | tnt                    | 07/18/2019 06:10 AM | Related to #3582  |
| 3032 | OsmoBTS                         | Bug     | New         | High     | (Wrong?) measurement of both RSSI and ToA on TCH channels                      | tnt                    | 11/26/2018 02:32 PM | Related to #2977,Related to #3032                                   |
| 2363 | OpenBSC                         | Support | New         | High     | migrate important branches from openbsc.git to new osmo-{msc,bsc,mgw,sgsn}.git | Osmocom CNI Developers | 09/12/2018 02:41 PM |   |
| 4074 | libosmocore                     | Bug     | New         | Normal   | LAPD timers completely broken  | Osmocom CNI Developers | 06/21/2019 04:12 PM | Related to #4074  |
| 3510 | OsmoBTS                         | Bug     | New         | Normal   | Make sure the ECU (Error Concealment Unit) is working correctly                | tnt                    | 05/15/2019 03:48 PM |   |
| 3966 | E1/T1 Hardware Interface        | Feature | In Progress | Normal   | finish the USB-E1 ICE40 prototype  | tnt                    | 04/30/2019 08:49 AM |   |
| 3965 | E1/T1 Hardware Interface        | Feature | In Progress | Normal   | ICE40 based USB E1 adapter   | tnt                    | 04/30/2019 08:48 AM | Related to #3965,Related to #3965,Related to #3965                  |
| 3054 | OsmoTRX                         | Feature | Stalled     | Normal   | Extended (11-bit) RACH support in OsmoTRX                                      | tnt                    | 02/03/2019 11:45 AM | Related to #1854,Related to #3054,Related to #3054,Related to #4006 |
| 64   | Miscellaneous Projects          | Bug     | New         | Normal   | osmo-bts-amp: 2.2uF capacitors next to PA need to be 0603, not 0805            | tnt                    | 02/21/2016 04:48 PM |   |
| 1974 | OsmoMSC                         | Feature | New         | Low      | VLR: high water mark on subscriber storage                                     | Osmocom CNI Developers | 07/18/2019 06:15 AM | Related to #1973  |
| 1973 | OsmoMSC                         | Feature | New         | Low      | VLR: efficient subscriber lookup   | Osmocom CNI Developers | 07/18/2019 06:15 AM | Related to #1973  |
| 3222 | OsmoTRX                         | Bug     | Stalled     | Low      | include (tested) example config files for usrp1, uhd/b200 as well as umtrx     | tnt                    | 10/20/2018 07:27 PM |   |
| 3142 | Cellular Network Infrastructure | Feature | New         | Low      | Further simplification of "NITB like" setups                                   | Osmocom CNI Developers | 04/05/2018 08:09 PM |   |
| 1576 | OsmoBTS                         | Feature | New         | Low      | consider using hLayer2 as a pointer storage                                    | Osmocom CNI Developers | 02/02/2017 04:11 PM | Related to #1755  |
| 1755 | OsmoBTS                         | Feature | New         | Low      | osmo-bts-sysmo L1: unify hLayer3 handling                                      | Osmocom CNI Developers | 02/02/2017 04:00 PM | Related to #1755  |