

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
5109	OpenVizsla USB tracer/analyzer	Bug	Resolved	Normal	reduce solder stop opening sizes for pads of U2, U3, U4 and U7	cibomahto	05/26/2021 06:23 PM	
5108	OpenVizsla USB tracer/analyzer	Bug	Resolved	Normal	adapt differential traces' properties to intended layer built-up for upcoming production run	cibomahto	04/11/2021 07:52 PM	
5098	OpenVizsla USB tracer/analyzer	Bug	Resolved	Normal	exported 'ov_ftdi.DWG' appears to be a DXF file	cibomahto	03/28/2021 06:11 PM	
5095	OpenVizsla USB tracer/analyzer	Feature	Resolved	Normal	export project in ASCII interchange format for other eCAD prgms	cibomahto	03/28/2021 04:40 PM	
5086	OpenVizsla USB tracer/analyzer	Feature	Resolved	Normal	place 3 fiducials	cibomahto	03/26/2021 12:32 PM	
5078	OpenVizsla USB tracer/analyzer	Feature	Resolved	Normal	round all SMD pads	cibomahto	03/18/2021 01:12 PM	
5073	OpenVizsla USB tracer/analyzer	Bug	Resolved	Normal	repair single via restrung rule violation	cibomahto	03/17/2021 01:38 PM	
4387	osmo-clock-gen	Bug	Resolved	Normal	wrong BOM attributes for ATSAMD21	mschramm	01/31/2020 05:21 PM	
4386	osmo-clock-gen	Bug	Resolved	Normal	Mini-USB footprint needs to have positioning drills for selected type	mschramm	01/30/2020 05:04 PM	
4241	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	Normal	measure insertion loss for two alternatives of RF adapter on VNA up to 3GHz	roh	11/21/2019 02:21 PM	
4231	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	Normal	connect /PERST line @NGFF to POWERGD (pin4 @X2)	mschramm	10/17/2019 06:37 PM	
4230	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	High	cross Rx/Tx on breakout board	mschramm	10/18/2019 03:31 PM	
4216	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	Normal	connect PCIe conn pin 7 on NGFF to GND	mschramm	10/17/2019 04:19 PM	
4211	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	Normal	find solution for inverted polarity of SIMx_DET (SIM present) switches and their altered pin designation on some modems for 2nd SIM	mschramm	09/24/2019 04:35 PM	
4210	M.2 (NGFF) WWAN modem USB breakout board	Feature	Resolved	Low	PCIe conn could be moved inwards by 3mm	mschramm	09/19/2019 05:22 PM	
4209	M.2 (NGFF) WWAN modem USB breakout board	Bug	Resolved	Normal	PWR_ON pull-down too strong (R9 = 10k) - modem won't switch on	mschramm	09/17/2019 03:43 PM	
4087	SIMtrace 2	Feature	Resolved	Low	remove bogus targets from build process and ftp dir	laforge	12/06/2019 07:14 PM	