

UmTRX - Feature #1517

U_FL (UMC) connectors are not reliable after few connections

02/19/2016 10:52 PM - 9600

Status:	New	Start date:	
Priority:	Normal	Due date:	
Assignee:	Andrey	% Done:	0%
Category:	Hardware	Spec Reference:	
Target version:	UmTRXv2.2		
Resolution:			
Description			
U_FL (UMC) connectors are not reliable after few connections.			
[Migrated from old Google Code tracker]			