

OsmoPCU - Bug #1925

Fix padding for MCS8 transition

01/24/2017 05:25 PM - msuraev

Status: New	Start date: 01/24/2017
Priority: High	Due date:
Assignee: lynxis	% Done: 0%
Category:	
Target version:	
Spec Reference:	
Description So far MCS8->MCS6 padding or MCS8->MCS3 padding is disabled as it was not supported by some L1 firmware.	

History

#1 - 01/24/2017 05:26 PM - msuraev

See gerrit 1513 for related discussion.

#3 - 08/17/2017 06:53 AM - laforge

- Assignee changed from arvind.sirsikar to sysmocom

#4 - 10/29/2017 06:47 PM - laforge

- Priority changed from Normal to High

#5 - 10/02/2018 03:46 PM - laforge

#6 - 04/15/2019 07:45 AM - laforge

- Assignee changed from sysmocom to lynxis