

OP25 - Bug #2172

HDU often missing in captures

04/22/2017 04:04 PM - stevie

Status: New	Start date:
Priority: High	Due date:
Assignee:	% Done: 0%
Category:	
Target version:	
Resolution:	Spec Reference:
Description When the centre frequency of the captured channel is offset from the centre frequency of the channel its often the case that the HDU is not captured. It appears that the demodulator is having trouble recognizing that a signal is present.	

History

#1 - 04/22/2017 04:14 PM - zecke

- Project changed from OP25j to OP25