

SDR (Software Defined Radio) - Bug #3126

Windows 10 Pro 1709: crash of rtl_test.exe

03/30/2018 02:16 PM - JWS

Status: New	Start date: 03/30/2018
Priority: Low	Due date:
Assignee:	% Done: 100%
Category:	
Target version:	
Resolution:	Spec Reference:
Description	
<p>Hi, I fixed the following crash using rtl_test.exe:</p> <p>Found 2 device(s): 0: å, , SN: NÚ@ 1: Realtek, RTL2838UHIDIR, SN: 00000001</p> <p>Using device 0: Generic RTL2832U OEM usb_open error -12 Failed to open rtl_sdr device #0.</p> <p>The fix is, to use version 1.0.22 of libusb.</p>	