

OsmoSDR - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
4938	Feature	Rejected	Normal	Telephone design	efistokl	01/08/2021 03:56 PM	
4937	Feature	Rejected	Normal	Beginner		01/08/2021 03:56 PM	
1473	Feature	Rejected	High	verify if 80Mhz rate between ADC and FPGA works	laforge	02/20/2016 08:23 PM	
1472	Feature	Rejected	Normal	connect ADSCK to a DQS capable FPGA pin	laforge	02/20/2016 08:23 PM	
1471	Feature	Rejected	High	implement and test FPGA flashing via sam3u	laforge	02/20/2016 08:23 PM	
1470	Feature	Rejected	High	implement DFU bootloader in first 16k of flash	laforge	02/20/2016 08:23 PM	
1469	Feature	Rejected	Normal	make sure sam3u chip id is present in Usb Serial Number	laforge	02/20/2016 08:23 PM	
1468	Feature	Rejected	Normal	try to fit 2.5mm audio jack footprint (UART) on back side	laforge	02/20/2016 08:23 PM	
1467	Feature	Rejected	Immediate	place "sysmocom" name into copper layer (back side)	laforge	02/20/2016 08:23 PM	
1466	Feature	Rejected	High	add footprint of 2x5pin 1.27mm pitch SWD connector	laforge	02/20/2016 08:23 PM	