

OP25 - Bug #2162

Fix bit-ordering in output for VC55.

04/22/2017 04:04 PM - stevie

Status: New	Start date:
Priority: High	Due date:
Assignee:	% Done: 0%
Category:	
Target version:	
Resolution:	Spec Reference:
Description VC55 output needs to be changed and verified using the VC55 hardware.	

History

#1 - 04/22/2017 04:15 PM - zecke

- Project changed from OP25j to OP25