

OsmoGSMTester - Bug #2245

osmo-bts cfg: fix band string

05/07/2017 12:50 AM - neels

Status: New	Start date: 05/07/2017
Priority: Low	Due date:
Assignee: osmo-gsm-tester	% Done: 0%
Category:	
Target version:	
Spec Reference:	
Description	
<p>currently the VTY config 'band' is set to 'GSM-1800' from resources.conf for various BTS models. That's not a valid value. While it doesn't seem to phase the BTS operation (at least sysmoBTS operates happily), this should rather be a valid value.</p> <p>Take the valid band values from osmo-bts and use these in osmo-gsm-tester:</p> <pre>OsmoBTS (bts) # band 450 Alias for GSM450 GSM450 450Mhz 480 Alias for GSM480 GSM480 480Mhz 750 Alias for GSM750 GSM750 750Mhz 810 Alias for GSM810 GSM810 810Mhz 850 Alias for GSM850 GSM850 850Mhz 900 Alias for GSM900 GSM900 900Mhz 1800 Alias for DCS1800 DCS1800 1800Mhz 1900 Alias for PCS1900 PCS1900 1900Mhz</pre>	
Related issues:	
Related to OsmoGSMTester - Feature #2230: osmo-gsm-tester: arfcn as resource	New 05/04/2017

History

#1 - 05/07/2017 12:51 AM - neels

- Related to Feature #2230: osmo-gsm-tester: arfcn as resource added

#2 - 05/14/2017 11:21 AM - laforge

- Assignee deleted (Osmocom CNI Developers)

#3 - 05/15/2017 12:58 PM - laforge

- Assignee set to osmo-gsm-tester