

OsmoBSC - Feature #2724

Improve default timers

12/08/2017 11:46 PM - laforge

Status: New	Start date: 12/08/2017
Priority: Normal	Due date:
Assignee: laforge	% Done: 100%
Category:	
Target version:	
Spec Reference:	
Description A lot of the timer default values have been chosen a decade ago with no good basis. Let's improve this. I've started Timers for related discussions.	
Subtasks:	
Bug # 2733: T3101 default is way too large at 10s	Closed
Bug # 2734: RF channel teradown timers (T3109) way too large	Closed
Related issues:	
Related to OsmoBSC - Bug #2756: T3113 default of 60s seems way too large	Closed 12/14/2017

History

#1 - 12/14/2017 11:26 AM - laforge

- Related to Bug #2756: T3113 default of 60s seems way too large added

#2 - 12/17/2017 02:28 PM - laforge

- Checklist item [] make sure to update the osmoBSC user manual timers section added