

## m.2 (NGFF) WWAN modem USB breakout board - Feature #4210

### PCIe conn could be moved inwards by 3mm

09/17/2019 03:27 PM - mschramm

<b>Status:</b>	Resolved	<b>Start date:</b>	09/17/2019
<b>Priority:</b>	Low	<b>Due date:</b>	
<b>Assignee:</b>	mschramm	<b>% Done:</b>	100%
<b>Category:</b>			
<b>Target version:</b>			
<b>Description</b>			
The PCIe x1 connector could get moved inwards by about 3mm. However, it sits tightly, so this change is optional.			

#### History

#1 - 09/18/2019 05:30 PM - mschramm

- Status changed from New to In Progress

#2 - 09/19/2019 05:22 PM - mschramm

- Status changed from In Progress to Resolved

- % Done changed from 0 to 100

#### Files

X2.jpg	83.2 KB	09/17/2019	mschramm
--------	---------	------------	----------