

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
4881	OsmoBSC	Bug	Feedback	Normal	osmo-bsc with unixsocket to osmo-el2tpd fails to bring up rbs6k (dug20+rrus12)	firs	01/01/2021 10:10 AM	