

OsmoBSC - Feature #3505

ttcn3: test inter-BSC HO with encryption enabled

08/28/2018 09:28 AM - neels

Status: New	Start date: 08/28/2018
Priority: Normal	Due date:
Assignee: neels	% Done: 0%
Category:	
Target version:	
Spec Reference:	
Description The initial implementation of inter-BSC HO (incoming) fails to apply the encryption configuration to the new lchan. Add a ttcn3 test that does inter-BSC HO with encryption enabled and make sure the encryption gets applied.	
Related issues: Related to OsmoBSC - Bug #2283: Inter-BSC hand-over is missing (BSC side) Resolved 05/22/2017	

History

#1 - 08/28/2018 09:28 AM - neels

- Related to Bug #2283: Inter-BSC hand-over is missing (BSC side) added

#2 - 08/28/2018 06:20 PM - neels

#3 - 08/28/2018 06:38 PM - neels