

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
4769	OsmocomBB	Bug	Resolved	Normal	gtm900b target: autodetection between MGCxGSMT and MG01GSMT hw is wrong	laforge	10/10/2020 03:36 PM	
4610	OsmocomBB	Bug	Resolved	High	OBB port on GTM900-B risks causing hw damage with fighting driver outputs on Calypso GPIO3/DTR line	laforge	10/11/2020 11:13 AM	Related to #4610
3652	OsmocomBB	Bug	New	Normal	Incorrect IMEISV setting in mobile application		10/12/2018 08:20 PM	