

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
2175	OP25	Feature	New	High	Update code for GNURadio 3.6 and later	stevie	04/22/2017 04:14 PM	
2173	OP25	Feature	New	High	Remove dependency on ET++		04/22/2017 04:14 PM	
2172	OP25	Bug	New	High	HDU often missing in captures		04/22/2017 04:14 PM	
2171	OP25	Feature	New	High	Use libfftw3 for IFFT/FFT functions.		04/22/2017 04:14 PM	
2169	OP25	Bug	New	High	First-cut of trunking support		04/22/2017 04:15 PM	
2162	OP25	Bug	New	High	Fix bit-ordering in output for VC55.		04/22/2017 04:15 PM	
2160	OP25	Feature	New	High	Add "datascope" to usrp_p25_rx.py		04/22/2017 04:16 PM	
2158	OP25	Feature	New	High	Create a shared library for decoding for WireShark and the decoder.		04/22/2017 04:16 PM	
2157	OP25	Feature	New	High	Fix "traffic" tab so it displays data for non-HDU data units		04/22/2017 04:16 PM	
2156	OP25	Feature	New	High	Implement forward error correction for HDU.		04/22/2017 04:16 PM	
2155	OP25	Feature	New	High	Replace FSK4 demodulation with IQ demodulator stage.		04/22/2017 04:16 PM	
2174	OP25	Feature	Closed	High	Recode Frank's C4FM demodulator in Python		04/25/2017 01:57 PM	
2163	OP25	Feature	Closed	High	DV Dongle support for IMBE decoding		04/25/2017 01:57 PM	
2161	OP25	Bug	Closed	High	Support OpenGL displays in usrp_p25_rx.py		04/25/2017 01:57 PM	
2159	OP25	Feature	Closed	High	Update WireShark patch for WireShark 1.2		04/25/2017 01:57 PM	
2154	OP25	Feature	Closed	High	Integrate IMBE decoding into decoder block.		04/25/2017 01:57 PM	
1699	OP25	Feature	Closed	High	Integrate IMBE decoding into decoder block.		05/03/2016 11:14 AM	