

## UmTRX - Feature #1516

### There are no port to control external equipment like PA

02/19/2016 10:52 PM - 9600

<b>Status:</b>	New	<b>Start date:</b>	
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Andrey	<b>% Done:</b>	0%
<b>Category:</b>	Hardware	<b>Spec Reference:</b>	
<b>Target version:</b>	UmTRXv2.2		
<b>Resolution:</b>			
<b>Description</b>			
There is no port to control external equipment such as a PA.			
[Migrated from old Google Code tracker]			