

## UmTRX - Feature #1518

### Upper limit of the clock is too low

02/19/2016 10:52 PM - 9600

<b>Status:</b>	New	<b>Start date:</b>	
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Andrey	<b>% Done:</b>	0%
<b>Category:</b>	Hardware	<b>Spec Reference:</b>	
<b>Target version:</b>	UmTRXv2.2		
<b>Resolution:</b>			
<b>Description</b>			
Upper limit of the clock is too low.			
[Migrated from old Google Code tracker]			