

## OsmoBTS - Bug #1578

### RSL MODE MODIFY can change multi-rate config, but not encryption parameters

02/23/2016 03:40 PM - laforge

<b>Status:</b>	New	<b>Start date:</b>	02/23/2016
<b>Priority:</b>	Low	<b>Due date:</b>	
<b>Assignee:</b>	osmith	<b>% Done:</b>	0%
<b>Category:</b>			
<b>Target version:</b>			
<b>Spec Reference:</b>			
<b>Description</b>			

#### History

---

#1 - 09/30/2018 11:14 AM - laforge

- Assignee set to osmith

might make sense to start with a BTS\_Tests.ttcn TTCN-3 test case to check modification of encryption parameters. That will then fail and should get fixed with a proper bugfix in osmo-bts.