

SIMtrace 2 - Bug #1705

re-integrate tracing + card reader modes into SIMtrace2 firmware (SAM3S)

05/09/2016 07:46 PM - laforge

Status: Stalled	Start date: 05/09/2016
Priority: High	Due date:
Assignee: tsaitgaist	% Done: 50%
Category: firmware	
Target version:	
Description the current laforge/cardemu branch breaks sim card tracing + card reader modes. Re-integrate and test those to have one firmware image working in all modes	
Related issues: Related to SIMtrace 2 - Bug #1704: test/port card emulation firmware for SAM3... In Progress 05/09/2016	

History

#1 - 01/12/2017 01:13 PM - laforge

- Priority changed from Normal to High

#2 - 02/28/2017 06:00 PM - laforge

- Status changed from New to In Progress

#3 - 04/26/2018 04:10 PM - laforge

- Assignee changed from laforge to tsaitgaist

#4 - 05/11/2018 04:29 PM - laforge

- Project changed from SIMtrace to SIMtrace 2

- Category deleted (SIMtrace firmware)

#5 - 06/13/2018 01:15 PM - tsaitgaist

- % Done changed from 0 to 50

#6 - 08/09/2018 12:14 PM - laforge

- Category set to firmware

#7 - 08/13/2018 04:54 PM - tsaitgaist

- Status changed from In Progress to Stalled

will do after cardem is ported on SIMtrace v2 hardware tracked in <https://osmocom.org/issues/1704>

#8 - 08/13/2018 04:54 PM - tsaitgaist

- Related to Bug #1704: test/port card emulation firmware for SAM3S based SIMtrace2 added